

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at 3414H, 3404B, & 3403B Wellheads, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/30/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	Electrical and Automation Equipment		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 4		

Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: LACT	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	8	400 BBLs	STEEL AST		40.808280,-103.859210
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		40.808520,-103.858880
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>430326</u>	Type:	<u>WELL</u>	API Number:	<u>123-36130</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				
Facility ID:	<u>433652</u>	Type:	<u>WELL</u>	API Number:	<u>123-37730</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				
Facility ID:	<u>433678</u>	Type:	<u>WELL</u>	API Number:	<u>123-37744</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				
Facility ID:	<u>434379</u>	Type:	<u>WELL</u>	API Number:	<u>123-38130</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Stained Soil at 3414H, 3404B, and 3403B Wellheads	petrie	09/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402489951	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248130
696302493	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248121