

Inspection Photos  
Operator: BP America  
API: 067-08880  
Date: 9/18/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass and sand dropseed, largely in a grazed condition.





Photo 3. View of the western cut-slope showing areas that remain sparse and where additional stabilization is needed. Erosion controls need to be installed to stabilize erosion on bare soils until stabilized with desirable perennial vegetation.





Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, squirreltail, and antelope bitterbrush.





Photos 5/6. Locked gate coming in (left) and leaving (right).