

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2020

Submitted Date:

09/24/2020

Document Number:

695103335**FIELD INSPECTION FORM**Loc ID 308253 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10351Name of Operator: WAPITI OPERATING LLCAddress: 1310 W SAM HOUSTON PKWY NCity: HOUSTON State: TX Zip: 77043**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist
Middlebrook, Sonny	575-445-6724/575-445-8610	smiddlebrook@wapitienergy.com	All Inspections
Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com	Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264828	WELL	PR	05/01/2014	GW	071-07731	VPR C 112	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Phone 5 & 6: CULVERT IS ALMOST COMPLETELY PLUGGED.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date:	10/24/2020

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	WEEDS		
Comment:	Phone 3: VEGETATION NOT MAINTAINED NEAR PUMPJACK.		
Corrective Action:	REMOVE OR MAINTAIN VEGETATION, COMPLY WITH RULE 603.f.	Date:	10/24/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type:	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Phone 4: BRADENHEAD IS NOT PLUMBED TO SURFACE.		
Corrective Action:	PLUMB BRADENHEAD TO SURFACE, COMPLY WITH RULE 608.e.	Date:	10/24/2020

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 264828 Type: WELL API Number: 071-07731 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103336	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255450