

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



Spill flowed from left to right in the drainage pictured.

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



**Downstream from produced water pool shown in next photo.
Operator was instructed to obtain water sample downstream
from this area to show background.**

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



Sep 29, 2020 11:13:57
37.19486N 104.90528W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Pool of suspected produced water in drainage

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



Drainage contained marshy grass

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



Looking from drainage where spill flowed up toward source of spill

Location Name: Vallejo 44-5 lease road Location ID/API #: Spill 478196



Sep 29, 2020 11:21:58
37.19170N 104.90491W

Source of leak was failure at this nipple.