


FOUR CORNERS ENERGY LLC – 10754
API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14
Inspection Date 10/1/2020



Location overview from SW anchor marker looking NE (left) to SE (right)

FOUR CORNERS ENERGY LLC – 10754
API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14
Inspection Date 10/1/2020



Sign at SW corner of tank battery.
Wrong operator information on sign.
Needs update emergency contact information and 911



Shut in wellhead.
Audible gas leak at tubing valve packing fitting.
Bradenhead valve not plumbed to surface.

FOUR CORNERS ENERGY LLC – 10754
API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14
Inspection Date 10/1/2020



**Tank Battery with earth berms.
Weeds inside berms.**



Tank Battery with improper tank labels.

FOUR CORNERS ENERGY LLC – 10754
API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14
Inspection Date 10/1/2020



**Separator with earth berms.
Weeds inside berms.**



Meter housing and off location flowlines

FOUR CORNERS ENERGY LLC – 10754
API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14
Inspection Date 10/1/2020



**100 bbl produced water tank ½+ full of oil/water.
No berms. Broken elbow on flowline.**



**Oil/water level in produced water tank
wth less than 2 feet freeboard.**

FOUR CORNERS ENERGY LLC – 10754
API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14
Inspection Date 10/1/2020



*Broken elbow
on flowline*

Close up of Broken elbow on flowline.



*Leaking
packing
fitting*

Audible leak on tubing valve packing fitting.