

Inspection Photos

API#107-06123

Operator: Bayless

Insp#: 692402572

Insp Date: 9/25/2020



Photo#1:

Over views of Location which has not been reclaimed.

September 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayless PA Grassy Creek Coal API#107-06123



Photo#2:
Access Road has not been reclaimed.

September 25, 2020



Photo#3:
Access Road has not been reclaimed.



Photo#4:
Northwest end of Location where erosion issues are evident.

September 25, 2020



Photo#5:
Close up of erosion at NW end of site.



Photo#6:
Close up of erosion at NW end of site..

September 25, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayless PA Grassy Creek Coal API#107-06123



Photo#7:
Weed concerns at site.



Photo#8:
Weed concerns at site.

September 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayless PA Grassy Creek Coal API#107-06123