

Inspection Photos

Location Name: South Canyon Fed

Location ID: 322299 & Remediation Project Number: 10464

Inspection Date: September 29, 2020



Location sign.



Monitoring well drill rig and solar powered SVE system.



Inspection Photos

Location Name: South Canyon Fed

Location ID: 322299 & Remediation Project Number: 10464

Inspection Date: September 29, 2020



Newly installed monitoring well (red circle) and the arroyo located north of the location.



Arroyo located north of the location.



Inspection Photos

Location Name: South Canyon Fed

Location ID: 322299 & Remediation Project Number: 10464

Inspection Date: September 29, 2020



View of the area where the impacted material from the pit was landfarmed. The larmfarm was located south of the location, adjacent to the access road.



View of the area where the impacted material from the pit was landfarmed. The larmfarm was located south of the location, adjacent to the access road.



Inspection Photos

Location Name: South Canyon Fed

Location ID: 322299 & Remediation Project Number: 10464

Inspection Date: September 29, 2020



Wellhead, note the unmarked riser (red area).



Separator, note the unmarked risers (red areas).

