

Inspection Photos

Operator: Southland Royalty
API: 067-09493
Date: 10/1/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Vegetation appears to be progressing here largely with grasses such as crested wheatgrass, in a grazed condition.




Photo 3. View of Russian knapweed within the northwestern project area. Approximately 200 individuals observed.



Photo 4. View of erosional rilling and bare soils on the well pad cut-slope. Additional stabilization is needed.



Photo 5. View of erosional channel, approximately 2.5 feet wide and 2 feet deep, within the southwestern cut-slope.



Photo 6. View of erosional channeling in the southeastern cut-slope. Wattle netting and debris present.



Photo 7. View of reference area comprised of grass field, largely with grazed grasses in a dormant vegetative condition.



Photos 8/9. Closed gate coming in (left) and leaving (right).