

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2020

Submitted Date:

10/07/2020

Document Number:

701100542**FIELD INSPECTION FORM**Loc ID 334884 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Byers, Jim            |              | jbyers@blm.gov                     |         |
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com |         |
| Kellerby, Shaun       |              | shaun.kellerby@state.co.us         |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 211371      | WELL | PR     | 10/10/1997  | GW         | 045-07131 | FEDERAL GM 42-4  | PR          |
| 273022      | WELL | PR     | 11/20/2005  | GW         | 045-10209 | FEDERAL GM 342-4 | PR          |
| 273023      | WELL | PR     | 11/18/2005  | GW         | 045-10207 | FEDERAL GM 442-4 | PR          |
| 273024      | WELL | PR     | 11/14/2005  | GW         | 045-10206 | FEDERAL GM 542-4 | PR          |

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted a Follow Up inspection to 05/13/2020 Inspection # 689704696 at TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W 4SENE, Location ID: 334884 in Garfield County, Colorado.  
Corrective actions have been addressed.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | WELLHEAD   |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | BATTERY  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | TANK LABELS/PLACARDS                                   |       |  |
| Comment:           | Tank capacity addressed. It's starting to faded again. |       |  |
| Corrective Action: |  | Date: |  |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 |       |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | TRASH |       |  |
| Comment:           |       |       |  |
| Corrective Action: |       | Date: |  |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |



**Inspected Facilities**Facility ID: 211371 Type: WELL API Number: 045-07131 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 273022 Type: WELL API Number: 045-10209 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 273023 Type: WELL API Number: 045-10207 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 273024 Type: WELL API Number: 045-10206 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Check Dams       | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
|                  |                 | Culverts                | Pass                  |               |                          |         |

Comment: [Storm water has been repaired.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 701100543    | Inspection 701100542 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264594">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264594</a> |