

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #1 Sign on Pump Jack. Well was PR during inspection.

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #2 weeds at wellhead.

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #3 Well was venting out of needle valve. If prior approval to vent gas has not been granted (via Sundry, Form 4), Immediately cease venting. Per COGCC Corrective Action Matrix.

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #4 Access road from the #1 well looking toward the area of impact.

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #5. This is the Area identified by COGCC staff on 4/8/2020, where oil staining was observed.

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #6 it appeared that the impacted area was tilled.

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #7 The foreground of photo is where impacts had been previously observed. The area in the background is a game trail (and perhaps a flowline corridor).

Inspection Photos
Remediation Project 15777
Inspection Date: 9/24/2020
All Photos taken by Kris Neidel



Photo #8 Close up of Game path.