

Inspection Photos

Operator: Hilcorp Energy
API: 067-09069
Date: 10/7/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of erosional channel, approximately 1.5 feet wide and deep, in the northeastern project area.

Musk thistle



Photod 4/5. View of musk thistles (on left) and scattered debris (on right) within the project area.



Photo 6. View of reference area vegetation comprised of gambel oak shrubland in a post-fire vegetative condition with other shrubs such as mountain mahogany, serviceberry as well as grasses and forbs such as squirreltail and Colorado rubberplant.