

Inspection Photos

Operator: Epic Energy
API: 067-05624
Date: 10/7/2020



Photo 1. View of project facilities in the eastern project area, facing northeastward from the access road. Revegetation is progressing within the project area with grasses, forbs, and sub-shrubs such as western wheatgrass, Colorado rubberplant, and black sage.



Photo 2. View of project facilities in the western project area facing westward from the access road.



Photo 3. View of erosional channel within the southwestern project area. Cobble is placed in channel. Wattles are degraded and only stakes/plastic netting remain.



Photos 4/5. View of black netting from degraded wattles within the project area.



Photo 6. View of reference area vegetation comprised of gambel oak shrubland in a post-fire vegetative condition with other shrubs such as mountain mahogany, serviceberry as well as grasses and forbs such as squirreltail and Colorado rubberplant.