

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2020

Submitted Date:

10/04/2020

Document Number:

693802464

FIELD INSPECTION FORMLoc ID 322103 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10754

Name of Operator: FOUR CORNERS ENERGY LLC

Address: 531 E 770 N

City: OREM State: UT Zip: 84097

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Williams, Larry	(801) 657-5780	larry@thesummitcompanies.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
,		dnr_cogccengineering@state.co.us	
Telecky, Barbara		btelecky@blm.gov	Durango
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208971	WELL	SI	10/01/2017	GW	033-06076	HUGUS FEDERAL 1	TA

General Comment:

COGCC staff performed a followup field inspection on 10/1/2020. Followup to inspection doc#685305269 on 08/28/2018. Issues were found requiring corrective action. CAs from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 10/14/2020
Type	BATTERY		
Comment:	Framed metal sign at location entrance (NE anchor maker). Sign not updated to reflect current operator. Operator has 60 days from time of Form 10 (change of operator) completion 8/14/2020.		
Corrective Action:	Install sign to comply with Rule 210.b. Install sign to comply with Rule 210.e.		Date: 10/14/2020
Emergency Contact Number:			
Comment:	None		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 10/14/2020
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds inside tank berms and on location.		
Corrective Action:	Comply with Rule 603.f .		Date: 10/13/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused Production tanks (2). Noted on previous inspection.		
Corrective Action:	Comply with Rule 603.f .		Date: 10/14/2020
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		37.649192,-108.972403

Comment: [Both tanks inside same berms.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		37.649192,-108.972403

Comment: [See unused equipment comment in housekeeping section.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [See weed comment in housekeeping section](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected FacilitiesFacility ID: 208971 Type: WELL API Number: 033-06076 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well shut in 4/2016. No MIT on record.
Well was found in state of Temporary Abandonment. Well TA longer than 6 months with no Form 4 submitted

Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: **Submit Form 4 as directed by Rule 319.b**Date: 11/04/2020

Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402502870	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261755
693802467	Inspection photos 10/1/2020	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261753