

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2020

Submitted Date:

10/05/2020

Document Number:

693700605**FIELD INSPECTION FORM**Loc ID 424707 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10503Name of Operator: RED HAWK PETROLEUM LLCAddress: 575 N DAIRY ASHFORD STE 201City: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boyd, William		wboyd@pedevco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424715	WELL	PR	08/01/2017	OW	123-34144	Planck 1-14H	EI
470960	SPILL OR RELEASE	AC			-	Planck 1-14H	EI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Stained soil at wellhead from inspection #696300729 has been removed. However oil from drum inside tank secondary containment is present; condensate/oil is present around flare and ECD

Corrective Action:

Dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/05/2020Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities						
Facility ID:	424715	Type:	WELL	API Number: 123-34144	Status: PR	Insp. Status: EI
Facility ID:	470960	Type:	SPILL OR	API Number: -	Status: AC	Insp. Status: EI

Environmental**Spill/Remediation:**

Comment: Spill #470960 was reported January 23, 2020 for failed gasket on treater. COGCC did not observe leaking treater or impacted material at the time of inspection.

Corrective Action: Submit Form 19 Supplemental Report with soil disposal manifests, confirmation soil sample analytailca data, and maps showing soil sample locations.

Date: 12/05/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402503388	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262125
693700606	Drum and staining inside secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262121
693700607	Impacted material around flare	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262122
693700608	Condensate at base of flare	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262123
693700609	Blowdown near ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262124