

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2020

Submitted Date:

10/05/2020

Document Number:

699700194

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Heil, John On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10091
 Name of Operator: BERRY PETROLEUM COMPANY LLC
 Address: 5201 TRUXTUN AVENUE #100
 City: BAKERSFIELD State: CA Zip: 90339
Findings:

- 2 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	
Wilbourn, Don		dwilbourn@bry.com	
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474500	SPILL OR RELEASE	AC	04/27/2020		-	Long Ridge J15	EI

General Comment:

On September 24, 2020 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of BERRY PETROLEUM COMPANY LLC (Berry operator #10091) Long Ridge J15 Spill/Release Point ID 474500, Remediation #15535.

Inspected Facilities

Facility ID: 474500 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: See Spill/Release Point ID 474500, Remediation #15535 for more information. Impacted material from the spill/release excavation is currently being landfarmed on the J15 Location (Location ID 335568). The excavation around the pipeline is still present along with a recently installed monitoring well. A cube container adjacent to the monitoring well contained a fluid with two distinct visible layers and a very strong hydrocarbon odor. The monitoring well is constructed with 4-inch PVC and the top of the monitoring well was open at time of inspection.

Corrective Action: Operator shall submit a Supplemental Form 19 requesting closure of Spill/Release Point ID 474500, with work proceeding under an approved Form 27 Remediation #15535. Date: 10/19/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402503434	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262149
402503830	20200924 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262562
699700195	20200924 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262147