

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/12/2020

Submitted Date:

10/12/2020

Document Number:

693700614**FIELD INSPECTION FORM**Loc ID 319436 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 88380Name of Operator: TINDALL OPERATING COMPANYAddress: P.O. BOX 4507City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Carrie Witzel		clwitzel@hotmail.com	
Charles Davis		dnroilgas@hotmail.com	
John Simms		jasimms9@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111628	PIT	AC			-	DOROTHY 1	EI
243480	WELL	PA	04/14/2017	OW	123-11271	DOROTHY 1	EI

**General Comment:**[COGCC Environmental Inspection, followup to pit closure.](#)

Inspected Facilities									
Facility ID:	111628	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	243480	Type:	WELL	API Number:	123-11271	Status:	PA	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: ☐Pit ID: 111628Lat: 40.592969Long: -103.904781Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: ☐Oil Accumulation: ☐2+ feet Freeboard: ☐Comment: Corrective Action: Date: 12/09/2020Pit excavation remains open. COGCC approved backfill of pit on 1/28/2020.Complete backfill of pit and begin final reclamation in accordance with Rule 1004. Submit Form 27 Supplemental to close Remediation Project 11611 upon completion of backfill.**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700615	Material stockpile on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267189">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267189</a>
693700616	Open pit excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267191</a>
693700617	Former tank battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267192">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267192</a>