

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/29/2020

Submitted Date:

10/12/2020

Document Number:

699700203

FIELD INSPECTION FORMLoc ID 322420 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	All Inspections
Hale, Steven	(970) 290-2912	shale@utahgascorp.com	Environmental Specialist
Fischer, Alex		alex.fischer@state.co.us	
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111214	PIT	AC			-	ATCHEE UNIT B-12-6S-104W	EI
210458	WELL	TA	03/01/2019	GW	045-06214	W R YOUNG CATTLE CO B-12-6-104-S	EI
438526	SPILL OR RELEASE	CL	08/07/2014		-	SPILL/RELEASE POINT	EI

General Comment:

On September 29, 2020 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of UTAH GAS OP LTD DBA UTAH GAS CORP (Utah Gas operator #10539) W R YOUNG CATTLE CO B-12-6-104-S Location ID 322420.

Utah Gas personnel Steven Hale and Telesto Solutions Inc. personnel Charlie Jensen were on location at time of inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2		STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Multiple holes observed in the tank battery secondary containment structure. Well on location is TA, no fluids were being discharged to the tank battery at time of inspection. Secondary containment is not sufficiently impervious to contain spilled or released materials.			
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure. Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 11/12/2020

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID:	<u>111214</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	------------	-------------	----------	---------	-----------	---------------	-----------

Facility ID:	<u>210458</u>	Type:	<u>WELL</u>	API Number:	<u>045-06214</u>	Status:	<u>TA</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

Facility ID:	<u>438526</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-----------------	-------------	----------	---------	-----------	---------------	-----------

Environmental**Spill/Remediation:**

Comment: [See Remediation #9341 for more information.](#)
[A solar powered soil vapor extraction \(SVE\) system related to Remediation #9341 was observed on location. A total of 5 SVE wells were observed on location at time of inspection.](#)

Corrective Action: [Operator shall provide an update to Remediation #9341 via an eForm F27.](#)

Date: 11/12/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700204	20200929 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267641