

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2020

Submitted Date:

10/08/2020

Document Number:

698100184**FIELD INSPECTION FORM**Loc ID 420164 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email                                 | Comment                         |
|---------------|-------|---------------------------------------|---------------------------------|
| , Laramie     |       | cogccnotifications@laramie-energy.com | <a href="#">All Inspections</a> |
| Fischer, Alex |       | alex.fischer@state.co.us              |                                 |

**Inspected Facilities:**

| Facility ID | Type            | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|-----------------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 420160      | WELL            | PR     | 07/01/2020  | GW         | 077-10119 | Kimball Creek 23-412D-995   | EI          |
| 420161      | WELL            | SI     | 03/01/2020  | GW         | 077-10120 | Kimball Creek 23-210D-995   | EI          |
| 427689      | TANK<br>BATTERY | AC     | 10/31/2010  |            | -         | Kimball Creek Pad 23-4C-995 | EI          |

**General Comment:**[COGCC Environmental Inspection. Weather conditions during inspection were Sunny with a temperature of 67 degrees Fahrenheit.](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Emergency contact number verified on 10/8/2020.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|                    |   |          |  |       |            |
|--------------------|---|----------|--|-------|------------|
| <b>Spills:</b>     |   |          |  |       |            |
| Type               | Area  | Volume   |  |       |            |
| Other              | WELLHEAD  | <= 1 bbl |  |       |            |
| Comment:           | Localized accumulation of stained gravel located southeast of day tank with chemical pumps. See photos. |          |  |       |            |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a.  |          |  | Date: | 11/08/2020 |
| Other              |   | <= 1 bbl |  |       |            |
| Comment:           | Localized accumulation of oil-stained soil between separators and tank battery, see photos.             |          |  |       |            |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a.  |          |  | Date: | 11/08/2020 |

In Containment: No

Comment:

☒ Multiple Spills and Releases?

|                           |   |  |  |                  |
|---------------------------|---|--|--|------------------|
| <b>Equipment:</b>         |   |  |  | corrective date  |
| Type: Ancillary equipment | # 1   |  |  |                  |
| Comment:                  | Leaking pump observed at chemical tank by wellheads. Operator was notified of this issue via phone on 10/8/2020. See photos.  |  |  |                  |
| Corrective Action:        | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. |  |  | Date: 11/08/2020 |

**Tanks and Berms:**

|                    |   |          |           |         |        |  |
|--------------------|---|----------|-----------|---------|--------|--|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |  |
| OTHER              | 3 | 300 BBLS | STEEL AST |         | ,      |  |
| Comment:           |   |          |           |         |        |  |
| Corrective Action: |   |          |           |         | Date:  |  |

**Paint**

|                  |                                |  |
|------------------|--------------------------------|--|
| Condition        |                                |  |
| Other (Content)  | 1 produced water, 2 condensate |  |
| Other (Capacity) |                                |  |
| Other (Type)     |                                |  |

**Berms**

|                    |  |                     |                     |             |
|--------------------|--|---------------------|---------------------|-------------|
| Type               | Capacity   | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate   |                     |                     | Adequate    |
| Comment:           | No holes or tears were observed in visible portion of tank battery liner on inspection date. |                     |                     |             |
| Corrective Action: |  |                     |                     | Date:       |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>420160</u> | Type: <u>WELL</u> | API Number: <u>077-10119</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>420161</u> | Type: <u>WELL</u> | API Number: <u>077-10120</u> | Status: <u>SI</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>427689</u> | Type: <u>TANK</u> | API Number: <u>-</u>         | Status: <u>AC</u> | Insp. Status: <u>EI</u> |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description           | URL   |
|--------------|-----------------------|---|
| 402506576    | INSPECTION SUBMITTED  | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5265183">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5265183</a> |
| 698100196    | 20201007 field photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5265182">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5265182</a> |