

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2020

Submitted Date:

10/15/2020

Document Number:

688500231**FIELD INSPECTION FORM**Loc ID 476479 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
KPK		cogcc@kpk.com	
Knop, Max	303-825-4822	MKnop@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Axelson, John		john.axelson@state.co.us	

General Comment:Environmental inspection done in response to complaint 200449220 regarding a leaking gas pipeline.

Environmental**Spills/Releases:**

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: _____

Comment: On 07/15/2020, the surface owner notified the operator of the discovery of a leaking gas pipeline on their property. The pipeline was exposed and repaired, but that excavation remains open. Surface owner alleges that the operator has stopped returning their communication. On 10/13/2020, the surface owner submitted Complaint #200449220 to the COGCC.

Corrective Action: 1. Submittal of a Form 19 as required by Rule 906.b.(1)A.2. Communication with the surface owner as required by Rule 906.c.(2). Completion of the work on the Thomas property, i.e. reclaiming the excavation.

Date: 10/22/2020

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Environmental inspection done in response to complaint 200449220 regarding a leaking gas pipeline.	canfielc	10/15/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500232	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271437