

Inspection Photos
Operator: Logos Operating
API: 067-05367
Date: 10/13/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing with smooth brome, western wheatgrass, and rubber rabbitbrush. Weeds such as Russian thistle and cheatgrass present. Russian thistle debris needs to be removed.



Photo 3. View of Russian thistles approx. 2-3 feet tall within the northwestern project area. Russian thistles will break off and become debris.




Photo 4. View of area within the northwestern project area where cobble BMP is filled with sediment and no longer functioning. Rilling is also occurring here.



Photo 5. closeup view of erosion and weeds within the northwestern project area.



Photo 6. View of reference area vegetation comprised of pinyon and juniper woodland with and understory of sagebrush, squirreltail, Indian ricegrass, and mixed forbs.