

KP Kauffman - COGCC Inspection Photos
Location: John Weigandt Consolidation OLF Release
Spill ID # 465402 Date 10/15/2020



Wellhead and signage; view northwest.



View of NW most bellhole style excavation; looking east toward the excavation at spill release point #465402.

New 3" SDR 11 HDPE pipe stung inside the cut end of the old 4" Consolidation flowline.

KP Kauffman - COGCC Inspection Photos
Location: John Weigandt Consolidation OLF Release
Spill ID # 465402 Date 10/15/2020



View of excavation at spill release point #465402. Looking South; Compromised section of the old flowline has been cut out and removed.



External corrosion hole identified in the side wall of the carbon steel flowline segment removed from the excavation.

KP Kauffman - COGCC Inspection Photos
Location: John Weigandt Consolidation OLF Release
Spill ID # 465402 Date 10/15/2020



View of excavation at spill release point #465402. Looking South; New 3" SDR 11 HDPE pipe has been stung/ sliplied inside the cut end of the old 4" Consolidation flowline.



View of SW most excavation; Looking east; New 3" HDPE pipe is being pulled inside the old 4" CS flowline.

KP Kauffman - COGCC Inspection Photos
Location: John Weigandt Consolidation OLF Release
Spill ID # 465402 Date 10/15/2020



View of 3" HDPE pipe slipline replacement pipe (taped) and the cut end of the out of service 1" CS gas supply line.



Aerial view of the approximate alignment of the John Weigandt Consolidation slipling project; the X's mark excavations and the location of spill ID 465402 is circled.