

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2020

Submitted Date:

10/02/2020

Document Number:

690900120

FIELD INSPECTION FORMLoc ID 323972 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Ramsey, Scott		scott.ramsey@state.co.us	
,		aaxelson@grizzlyenergyllc.com	
Heil, John		john.heil@state.co.us	
Arauz, Steven		steven.arauza@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	
Ghan, Scott	970 876-1959	sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211383	WELL	PR	07/01/2020	GW	045-07143	GIBSON GULCH UNIT 13-29	SI
466240	SPILL OR RELEASE	CL	10/18/2019		-	Gibson Gulch Unit-66S91W/29SWSW 323972	EI

General Comment:

On September 30, 2020, COGCC Environmental Staff (Alex Fischer and John Heil), Engineering Staff (Craig Burger and Aaron Katz), and Field Inspector Scott Ramsey conducted a field inspection and environmental inspection of Grizzly Operating, LLC (Grizzly) Gibson Gulch UNIT-66S91W /29SWSW (Location ID: 323972). The inspection was a follow up to Spill ID 466240 and REM 11050. Weather was sunny and temperature in the upper 70 degrees Fahrenheit.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds within livestocked fenced area.		
Corrective Action:	Comply with Rule 603.f .		Date: 10/16/2020
Type	UNUSED EQUIPMENT		
Comment:	Ladder stairs lying on the ground between the well head and condensate tank. Condensate tank LOTO. Note: CA date is the CA date from Insp Doc # 700700253.		
Corrective Action:	Comply with Rule 603.f .		Date: 04/15/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE					,	
Comment:	Tank adjacent to the well head.					
Corrective Action:	Move equipment to comply with minimum 75 foot setback as per Rule 605.a.8.				Date:	12/02/2020

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents	#	Capacity	Type			Tank ID	SE GPS		
CONDENSATE	1						,		
Comment:	Tank open to the atmosphere.								
Corrective Action:	Close and seal tank.							Date:	10/05/2020

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: <u>211383</u>	Type: <u>WELL</u>	API Number: <u>045-07143</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>466240</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>

COGCC Comments

Comment	User	Date
<p>An approximate 30' by 20' by 8' in depth excavation fenced off with livestock fencing was observed.</p> <p>One monitoring well was observed east of the open excavation and within the footprint of the formerly excavated area (See Doc #402351242).</p> <p>Weeds were observed throughout the livestock fenced area.</p> <p>Flow lines were observed in the excavation.</p> <p>Evidence of surface water run on into the excavation was observed.</p> <p>An approximate 5 cubic yard stockpile of soil and gravel was observed in the southeast area of the livestock fenced area.</p> <p>A condensate tank, open to the atmosphere, the tank valve was LOTO and the tank was adjacent to the well head.</p> <p>Stairs were observed lying on the ground between the tank and the well head.</p> <p>The well was LOTO.</p> <p>It is suggested that the operator put signage on the tank indicating that it is out of service.</p>	fischera	10/02/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402502503	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261373
690900121	GG Location ID 323972 Spill ID 466249 REM 14050 20200930 Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261371