

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/12/2020

Submitted Date:

10/12/2020

Document Number:

693700614

**FIELD INSPECTION FORM**

Loc ID 319436 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 88380  
Name of Operator: TINDALL OPERATING COMPANY  
Address: P.O. BOX 4507  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
John Simms		jasimms9@gmail.com	
Charles Davis		dnroilgas@hotmail.com	
Carrie Witzel		clwitzel@hotmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111628	PIT	AC			-	DOROTHY 1	EI
243480	WELL	PA	04/14/2017	OW	123-11271	DOROTHY 1	EI

**General Comment:**

[COGCC Environmental Inspection, followup to pit closure.](#)

**Inspected Facilities**

Facility ID: 111628 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 243480 Type: WELL API Number: 123-11271 Status: PA Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined:                      Pit ID: 111628              Lat: 40.592969              Long: -103.904781

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_                      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment: Pit excavation remains open. COGCC approved backfill of pit on 1/28/2020.

Corrective Action: \_\_\_\_\_

Complete backfill of pit and begin final reclamation in accordance with Rule 1004. Submit Form 27 Supplemental to close Remediation Project 11611 upon completion of backfill.

Date: 12/09/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402508847	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267201">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267201</a>
693700615	Material stockpile on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267189">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267189</a>
693700616	Open pit excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267191</a>
693700617	Former tank battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267192">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267192</a>