

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign not updated to reflect current operator. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	01/15/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216734 Type: WELL API Number: 069-05156 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 10/12/2020 at approximately 14:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Blackrock Energy Clarks Lake MSSU N-1 location #307068 in Larimer County, Colorado. While there, I observed that the wellhead sign had not been updated to reflect the current operator. During this inspection the following possible compliance issues were observed: Rule 210.e. with a corrective action date of 1/15/2021. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	10/12/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402509064	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267742
697002199	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5267737