

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2020

Submitted Date:

10/19/2020

Document Number:

700701717

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 335068 \_\_\_\_\_ Ramsey, Scott \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: PO BOX 370  
 City: PARACHUTE State: CO Zip: 81635
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 20 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210475	WELL	PR	04/12/1995	GW	045-06231	CLOUGH 20	PR
284621	WELL	PR	05/08/2006	GW	045-12244	CLOUGH RWF 323-15	PR
284622	WELL	PR	05/08/2006	GW	045-12243	CLOUGH RWF 413-15	PR
284623	WELL	PR	10/20/2008	GW	045-12242	CLOUGH RWF 524-15	PR
284624	WELL	PR	10/19/2008	GW	045-12241	CLOUGH RWF 514-15	PR
284625	WELL	PR	05/08/2006	GW	045-12240	CLOUGH RWF 523-15	PR
284626	WELL	PR	09/21/2006	GW	045-12239	CLOUGH RWF 424-15	PR
284627	WELL	PR	04/02/2007	GW	045-12238	CLOUGH RWF 23-15	PR
284628	WELL	PR	04/02/2007	GW	045-12237	CLOUGH RWF 423-15	PR
284629	WELL	PR	05/08/2006	GW	045-12236	CLOUGH RWF 414-15	PR
284630	WELL	PR	10/20/2008	GW	045-12235	CLOUGH RMV 157-15	PR
284641	WELL	PR	09/30/2008	GW	045-12246	CLOUGH RWF 324-15	PR
284642	WELL	PR	04/02/2007	GW	045-12245	CLOUGH RWF 314-15	PR
294713	WELL	PR	09/30/2008	GW	045-15577	CLOUGH RWF 534-15	PR

**General Comment:**

COGCC Inspection Report Summary

On Monday 10/19/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Clough 20, at Location # 335068 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- BMP's require maintenance(sediment traps, evidence of run off)
- Unused equipment (poly piping)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	polly piping on west side of location		
Corrective Action:	remove unused equipment	Date:	11/19/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 14		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	shared containment with condensate tank				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210475	Type:	WELL	API Number:	045-06231	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284621	Type:	WELL	API Number:	045-12244	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284622	Type:	WELL	API Number:	045-12243	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284623	Type:	WELL	API Number:	045-12242	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284624	Type:	WELL	API Number:	045-12241	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284625	Type:	WELL	API Number:	045-12240	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284626	Type:	WELL	API Number:	045-12239	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284627	Type:	WELL	API Number:	045-12238	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 284628	Type: WELL	API Number: 045-12237	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: producing				
Corrective Action:				Date:
Facility ID: 284629	Type: WELL	API Number: 045-12236	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: producing				
Corrective Action:				Date:
Facility ID: 284630	Type: WELL	API Number: 045-12235	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: producing				
Corrective Action:				Date:
Facility ID: 284641	Type: WELL	API Number: 045-12246	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: producing				
Corrective Action:				Date:
Facility ID: 284642	Type: WELL	API Number: 045-12245	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: producing				
Corrective Action:				Date:
Facility ID: 294713	Type: WELL	API Number: 045-15577	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: producing				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [BMP's require maintenance\(sediment traps, evidence of run off\) see photos](#)

Corrective Action: [repair all BMP's](#)

Date: 11/09/2020

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701723	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5273406">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5273406</a>