

Inspection Photos

Operator: Hilcorp Energy
API: 067-08485
Date: 10/15/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner of the working area facing westward. Vegetation is grazed, but appears to be progressing with grasses such as western wheatgrass and sand dropseed.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Drainage diversion is cobble-lined. Scattered musk thistles and Russian thistles need to be removed and properly disposed of.



Photo 4. View of reference area vegetation comprised of sand bar willow, western wheatgrass, smooth brome, and narrowleaf cottonwood.