

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/29/2020

Submitted Date:

10/14/2020

Document Number:

699700205**FIELD INSPECTION FORM**Loc ID 322292 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	All Inspections
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections
Fischer, Alex		alex.fischer@state.co.us	
Hale, Steven	(970) 290-2912	shale@utahgascorp.com	Environmental Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210169	WELL	PA	09/30/2019	GW	045-05058	KELLY-YOUNG-JENSEN B-1	EI
476600	SPILL OR RELEASE	CL			-	Kelly-Young-Jensen B-1	EI

General Comment:

On September 29, 2020 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of UTAH GAS OP LTD DBA UTAH GAS CORP (Utah Gas operator #10539) KELLY-YOUNG-JENSEN B-1 Location ID 322292.

Inspected Facilities									
Facility ID:	<u>210169</u>	Type:	<u>WELL</u>	API Number:	<u>045-05058</u>	Status:	<u>PA</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>476600</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 1

Comment: See Spill/Release ID 476600 for more details. 9/29/2020 the well on location has been plugged and abandoned, the location is in the process of being reclaimed. Operator reported in a meeting on 9/29/2020 that the material with inorganic exceedances was removed from location before the reclamation process began.

Corrective Action: Operator shall submit an eFrom 4 with analytical reports to verifying that the material with inorganic exceedances has been removed.

Date: 11/14/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402511388	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5270704
699700207	20200929 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5270703