

# Inspection Photos

API: 043-06196

Operator: JAVERNICK OIL

Inspection Date: 10/19/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road. The access road has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 2.** Facing northwest toward the location. The location has not been recontoured and reclaimed. There is an open hole and soil pile at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 3.** Facing southwest at the location. The cut slope is shown in the right side of the o. The location will need to be recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 4.** There is an open hole which is about 4.5 ft. deep shown by shovel placed in the hole. There is cement debris next to the hole which appears to be from plugging the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020