

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2020

Submitted Date:

10/15/2020

Document Number:

699801930

**FIELD INSPECTION FORM**

Loc ID: 334507    Inspector Name: De Paolo, Corey    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER    State: CO    Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277500	WELL	PR	10/29/2007	GW	077-08876	HELLS GULCH FEDERAL 2-9	PR
277501	WELL	PR	02/01/2015	GW	077-08875	HELLS GULCH FEDERAL 2-10	PR
277502	WELL	PR	09/19/2017	GW	077-08874	HELLS GULCH FEDERAL 2-15	PR
277503	WELL	PR	11/18/2008	GW	077-08873	HELLS GULCH FEDERAL 2-16	PR
281422	WELL	PR	09/01/2018	GW	077-08962	HELLS GULCH FEDERAL 2-7	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Thursday 10/15/20 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Hells Gulch Federal /2-10 Pad, Location #334507 in Mesa County Colorado.  
 While there, I observed normal production operations.  
 During this inspection the following possible compliance issues were observed: Wellhead sign weathered and not legible. See photo #2024 with a corrective action date of 1/15/21. Culvert by access gate inlet blocked by rip rap and sediment. See photo #2021. Culvert capacity reduced by sediment accumulation. See photo #2022. With a corrective action date of 10/30/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead sign weathered and not legible. See photo #2024		
Corrective Action:	Operators shall maintain signs in a legible condition, and shall replace damaged signs.		Date: 01/15/2021
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellhead		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Centralized containment	
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>277500</u>	Type:	<u>WELL</u>	API Number:	<u>077-08876</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>277501</u>	Type:	<u>WELL</u>	API Number:	<u>077-08875</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>277502</u>	Type:	<u>WELL</u>	API Number:	<u>077-08874</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>277503</u>	Type:	<u>WELL</u>	API Number:	<u>077-08873</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>281422</u>	Type:	<u>WELL</u>	API Number:	<u>077-08962</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Berms						
Sediment Traps						
Check Dams						
Ditches						
		Ditches				
		Rip Rap				
		Gravel				
		Berms				
		Check Dams				
		Culverts	Fail			Culvert inlet blocked by rip rap and sediment
Gravel						
Rip Rap						

Comment: [Culvert by access gate inlet blocked by rip rap and sediment. See photo #2021. Culvert capacity reduced by sediment accumulation. See photo #2022](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 10/30/2020

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402512709	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271852</a>
699801931	Photos for Insp. #699801930	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271848</a>