

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2020

Submitted Date:

10/16/2020

Document Number:

700701710**FIELD INSPECTION FORM**

Loc ID 311629	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>16</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279768	WELL	PR	09/06/2005	GW	045-11085	CLOUGH RWF 531-16	PR
280007	WELL	PR	09/13/2005	GW	045-11142	CLOUGH RWF 41-16	PR
280008	WELL	PR	09/13/2005	GW	045-11143	CLOUGH RWF 341-16	PR
280009	WELL	PR	06/08/2006	GW	045-11144	CLOUGH RWF 31-16	PR
280010	WELL	PR	09/13/2005	GW	045-11145	CLOUGH RWF 431-16	PR
280015	WELL	PR	06/08/2006	GW	045-11150	CLOUGH RWF 541-16	PR
280016	WELL	PR	10/12/2006	GW	045-11151	CLOUGH RWF 42-16	PR
280017	WELL	PR	09/13/2005	GW	045-11152	CLOUGH RWF 441-16	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 10/16/20 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Clough 7, at Location # 311629 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Riling and run on north west side of location behind separators, BMP's need to be addressed
- Chemical tank label at well heads is faded and is eligible

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	sinage is not ledgible		
Corrective Action:	repair signage	Date:	11/06/2020
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

Equipment:				corrective date
Type: Plunger Lift	# 13			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 7			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 13			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 13			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	chemical tank at well heads			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	shared containment with condensate tanks					
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	80 bbl tank in shared containment with condensate tanks					
Corrective Action:						

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	279768	Type:	WELL	API Number:	045-11085	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280007	Type:	WELL	API Number:	045-11142	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280008	Type:	WELL	API Number:	045-11143	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280009	Type:	WELL	API Number:	045-11144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280010	Type:	WELL	API Number:	045-11145	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280015	Type:	WELL	API Number:	045-11150	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280016	Type:	WELL	API Number:	045-11151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	280017	Type:	WELL	API Number:	045-11152	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				

Comment: [Riling and run on north west side of location behind separators, BMP's need to be addressed](#)

Corrective Action: [repair all BMP's](#)

Date: 11/06/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402513337	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272351
700701714	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272348