

Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



Photo #2091 from entrance to location.



Photo #2092 Culvert inlet collapsed and sediment accumulation.

Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



Photo #2089 approximate culvert location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



Photo #2094 Gully erosion.



Photo #2097 rill erosion.

Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



Photo #2095 sediment trap.



Photo #2096 sediment migrating off of location.