

Issue Report

Chaplin Limon 2-19, 073-06163



Report created on October 26, 2020

Captured: October 20, 2020



Type	Count
Other	3

No.	Summary	Type	Created	Status
3	Tree's growing on south side of location with some stressed vegetation all fenced in.	Other	Oct 26, 2020 at 6:40pm	Open
2	Tree growing on south side of location	Other	Oct 26, 2020 at 6:39pm	Open
1	Pumping unit fenced with steel panels	Other	Oct 26, 2020 at 6:37pm	Open

Other



No.	Summary	Created	Status
3	Tree's growing on south side of location with some stressed vegetation all fenced in.	Oct 26, 2020 at 6:40 PM	Open
2	Tree growing on south side of location	Oct 26, 2020 at 6:39 PM	Open
1	Pumping unit fenced with steel panels	Oct 26, 2020 at 6:37 PM	Open

No. 1 OPEN**Captured:** Oct 20, 2020 at 11:12am**Type**
Other**Lat/Long**
39.25329, -103.71228**Summary**
Pumping unit fenced with steel panels**Created**
Oct 26, 2020 at 6:37pm by Craig Quint

No. 2 OPEN**Captured:** Oct 20, 2020 at 11:12am**Type**
Other**Lat/Long**
39.25311, -103.71217**Summary**
Tree growing on south side of location**Created**
Oct 26, 2020 at 6:39pm by Craig Quint

No. 3 OPEN**Captured:** Oct 20, 2020 at 11:12am**Type**
Other**Lat/Long**
39.25311, -103.71211**Summary**
Tree's growing on south side of location with some stressed vegetation all fenced in.**Created**
Oct 26, 2020 at 6:40pm by Craig Quint