



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**BCU 42-31-198**

**API: 05-103-10874**

**Inspection: 700403936**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well.**

**BCU 42-31-198**

**API: 05-103-10874**

**Inspection: 700403936**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Separator.**

**BCU 42-31-198**

**API: 05-103-10874**

**Inspection: 700403936**





40.01499, -108.42849, 6820.1ft, 49°  
10/28/2020 02:00:34 PM



40.01513, -108.42838, 6825.1ft, 32°  
10/28/2020 02:00:01 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Tank with secondary container liner holes.**

BCU 42-31-198

API: 05-103-10874

Inspection: 700403936





40.01519, -108.42836, 6809.9ft, 347°  
10/28/2020 01:57:45 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Hole in tank liner.**

**BCU 42-31-198**

**API: 05-103-10874**

**Inspection: 700403936**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 7. Hole in tank liner.**

**BCU 42-31-198**

**API: 05-103-10874**

**Inspection: 700403936**