

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2020

Submitted Date:

10/28/2020

Document Number:

699501840**FIELD INSPECTION FORM**Loc ID 453512 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 1125 17TH STREET SUITE 550City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453504	WELL	PR	06/01/2019		123-46158	HDI KF 10-5H	PR
453505	WELL	PR	07/01/2019		123-46159	HDI KF 10-11H	PR
453506	WELL	PR	06/01/2019		123-46160	HDI KF 10-4H	PR
453508	WELL	PR	07/01/2019		123-46162	HDI KF 10-7H	PR
453510	WELL	PR	07/01/2019		123-46164	HDI KF 10-9H	PR
453511	WELL	PR	06/01/2019		123-46165	HDI KF 10-3H	PR
453513	WELL	PR	07/01/2019		123-46166	HDI KF 10-8H	PR
453514	WELL	PR	06/01/2019		123-46167	HDI KF 10-1H	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Red AG fencing		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wooden fence around location		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric / automation		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLs	FIBERGLASS AST		,
Comment:	538 BBK				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	500 BBLs	STEEL AST		,
Comment:	538 BBL				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected Facilities

Facility ID: <u>453504</u>	Type: <u>WELL</u>	API Number: <u>123-46158</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453505</u>	Type: <u>WELL</u>	API Number: <u>123-46159</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453506</u>	Type: <u>WELL</u>	API Number: <u>123-46160</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453508</u>	Type: <u>WELL</u>	API Number: <u>123-46162</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453510</u>	Type: <u>WELL</u>	API Number: <u>123-46164</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453511</u>	Type: <u>WELL</u>	API Number: <u>123-46165</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453513</u>	Type: <u>WELL</u>	API Number: <u>123-46166</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453514</u>	Type: <u>WELL</u>	API Number: <u>123-46167</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing WellComment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were clear, windy, recent snow.	medinaj	10/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501841	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5280990