

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #2155 from entrance to location.



Photo #1175 from inspection #699801094 conducted on 5/13/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #2157 Tank label and placards are weathered and not legible.



Photo #1179 from inspection #699801094 conducted on 5/13/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #2156 Tank by wellhead is not properly labeled.



Photo #2158 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #2159 Vegetation growing on tank containment berm.