

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #2162 from entrance to location.



Photo #2163 from entrance to location.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654




Photo #1631 from inspection #699801520 conducted on 7/28/20.



Photo #2164 Tank capacity, contents and NFPA labels weathered and not legible.



## Inspection Photos

**Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW**

**Location ID: 312654**



**Photo #1632 from inspection #699801520 conducted on 7/28/20.**



**Photo #2165 Multiple places with debris on location.**



## Inspection Photos

**Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW**

**Location ID: 312654**



**Photo #1633 from inspection #699801520 conducted on 7/28/20.**



**Photo #2166 Multiple places with debris on location.**