

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2020

Submitted Date:

11/02/2020

Document Number:

699802036

**FIELD INSPECTION FORM**Loc ID 312654 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
, Engineering		dnr_cogccengineering@state.co.us	
Graves, Jim		mrinc20@maralexinc.com	
Pesicka, Conor		conor.pesicka@state.co.us	
, BLM		jbyers@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222089	WELL	SI	05/01/2012	GW	077-08691	SULFUR GULCH 9-98-10 2	SI

**General Comment:****COGCC Inspection Report Summary**

On Monday 11/2/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow inspection at MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW, Location #312654 in Mesa County Colorado.

Refer to document #699801520 inspection conducted on 7/28/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Tank capacity, contents and NFPA labels weathered and not legible. See photo #1631 and #2164 with a previous corrective action date of 7/27/20. Multiple places with debris on location. See photo #1632, #2165, #1633 and #2166 with a previous corrective action date of 5/11/20. MIT required on well. With a previous corrective action date of 7/27/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Tank capacity, contents and NFPA labels weathered and not legible. See photo #1631 and #2164.			
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with tank capacity, contents and NFPA labels. Properly label tank.			Date: 07/27/2020
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Multiple places with debris on location. See photo#1632 ,#2165, #1633 and #2166.			
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.			Date: 05/11/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Hog panels			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Deadman # & Marked	# 4			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	STEEL AST		,	
Comment:	Capacity and contents not labeled					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 222089 Type: WELL API Number: 077-08691 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well last produced October 2003. Last MIT performed 9/19/14.Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Perform MIT on well.Date: 07/27/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Berms				
Berms						
		Ditches				
		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802037	Photos for Insp. #699802036	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282910">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282910</a>