

Inspection Photos

11/02/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335889

Garfield, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335889



Photo 1: Photo taken from the west end of the Location, facing northeast. Photos show BMPs remain missing or insufficient to stabilize the cut slopes on the northern and western ends of the Location.



Photo 2: Photo taken from the west end of the Location, facing northeast. Photo shows BMPs remain missing or insufficient to stabilize the cut slopes on the western ends of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 3: Photo taken from the northwest corner of the Location, facing northeast. Photo shows BMPs remain missing or insufficient to stabilize the slopes on the north end of the Location.

Photo 4: See comments under photo 3

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 5: Photo taken from the north end of the Location, facing northeast. Photo shows remnants of mulch that was applied to the northern slopes behind the tank battery. Photo shows BMP is insufficient to stabilize the slopes on the north end of the Location.



Photo 6: Photo taken from the north end of the Location, facing northeast. Photo shows BMPs remain missing or insufficient to stabilize the cut slopes on the north ends of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 7: Photo taken from the north end of the Location, facing east. Photo shows BMPs remain missing or insufficient to stabilize the cut slopes on the north ends of the Location.



Photo 8: Photo taken from the north end of the Location, facing northwest. Photo shows BMPs remain missing or insufficient to stabilize the cut slopes on the north ends of the Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335889



Photo 9: Photo taken from the northeast end of the Location, facing west. Photo shows BMPs remain missing or insufficient to stabilize the cut slopes on the north ends of the Location.



Photo 10: Photo taken from the access road, facing west. Photo shows interim slopes below the “storage area”. Photo shows Operator has installed erosion netting to help stabilize the slopes east and west of the “storage area”. BMP appears to be in proper functioning condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 11: Photo taken from the access road, facing west. Photo shows interim slopes below the “storage area”. Operator has installed erosion netting to help stabilize the slopes east and west of the “storage area”. BMP appears to be in proper functioning condition.