

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2020

Submitted Date:

11/03/2020

Document Number:

700701817

FIELD INSPECTION FORM

Loc ID 323879 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211072	WELL	PR	05/01/1994	GW	045-06830	SHAEFFER 18-5 (E18E)	SI

General Comment:**COGCC Inspection Report Summary**

On Tuesday 11/3/20 at approximately 1330, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus E18E, at Location # 323879 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Sediment migration from location on north side/riling is evident, along with sediment choking out vegetation. Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Bird Protectors	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Plunger Lift	# 1	
Comment:			
Corrective Action:			Date:
Type:	Gas Meter Run	# 2	
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211072 Type: WELL API Number: 045-06830 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				

Comment: Sediment migration from location on north side/riling is evident, along with sediment choking out vegetation.

Corrective Action: Repair all BMP's

Date: 11/24/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701823	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5283653