

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/28/2020

Submitted Date:

10/28/2020

Document Number:

697002330**FIELD INSPECTION FORM**
 Loc ID 323006 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name   | Phone | Email                         | Comment |
|----------------|-------|-------------------------------|---------|
| ,              |       | cogccinspections@anadarko.com |         |
| Pesicka, Conor |       | conor.pesicka@state.co.us     |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 244627      | WELL | PR     | 11/01/2018  | OW         | 123-12422 | STROH 2       | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: [No emergency contact number is posted at the tank battery. See attached photo.](#)Corrective Action: [Install sign to comply with Rule 210.b.](#)

Date: 01/29/2021

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                            |       |  |
|--------------------|----------------------------|-------|--|
| <b>Fencing/:</b>   |                            |       |  |
| Type               | WELLHEAD                   |       |  |
| Comment:           | <a href="#">Chain link</a> |       |  |
| Corrective Action: |                            | Date: |  |
| Type               | LOCATION                   |       |  |
| Comment:           | <a href="#">Chain link</a> |       |  |
| Corrective Action: |                            | Date: |  |

|                                   |   |       |                 |
|-----------------------------------|---|-------|-----------------|
| <b>Equipment:</b>                 |   |       | corrective date |
| Type: Bradenhead                  | # 1   |       |                 |
| Comment:                          | <a href="#">Bradenhead valve is exposed at surface.</a> |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Emission Control Device     | # 1   |       |                 |
| Comment:                          | <a href="#">Pilot is on</a>                             |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Plunger Lift                | # 1   |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Horizontal Heated Separator | # 1   |       |                 |

|                           |   |       |            |
|---------------------------|---|-------|------------|
| Comment:                  |   | Date: |            |
| Corrective Action:        |   | Date: |            |
| Type: Ancillary equipment | # 2   |       |            |
| Comment:                  | Automation array and ECD scrubber                 | Date: |            |
| Corrective Action:        |   | Date: |            |
| Type: Bird Protectors     | # 2   |       |            |
| Comment:                  |   | Date: |            |
| Corrective Action:        |   | Date: |            |
| Type: Gas Meter Run       | # 1   |       |            |
| Comment:                  | Calibration card is outdated. See attached photo. | Date: |            |
| Corrective Action:        | Measure gas per Rule 329.                         | Date: | 01/29/2021 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | #                                 | Capacity | Type           | Tank ID | SE GPS |
|--------------------|-----------------------------------|----------|----------------|---------|--------|
| PRODUCED WATER     | 1                                 | 100 BBLs | PBV FIBERGLASS |         |        |
| Comment:           | Produced water vault is anchored. |          |                |         |        |
| Corrective Action: |                                   |          |                |         |        |
|                    |                                   |          |                | Date:   |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Metal    | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |  |  |
|--|--|--|
|  |  |  |
|--|--|--|

|                      |            |                       |            |                  |
|----------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities |            |                       |            |                  |
| Facility ID: 244627  | Type: WELL | API Number: 123-12422 | Status: PR | Insp. Status: PR |
| Producing Well       |            |                       |            |                  |
| Comment:             | PR         |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| <p><b>COGCC Inspection Report Summary</b></p> <p>On Wednesday 10/28/2020 at approximately 13:45 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Stroh #2 location #323006 in Weld County, Colorado.</p> <p>While there, I observed that no emergency contact number was posted at the tank battery and the DCP meter calibration card was outdated. During this inspection the following possible compliance issues were observed: Rule 210.b. with a corrective action date of 1/29/2021, Rule 329. with a corrective action date of 1/29/2021.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | petersont | 10/28/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402520957    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5279457">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5279457</a> |
| 697002331    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5279436">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5279436</a> |