

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /9-41

Location ID: 432260



Photo #2172 from SW corner of location



Photo #2173 from SW corner of location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /9-41

Location ID: 432260



Photo #2175 Culvert inlet and outlet blocked by sediment.



Photo #2176 Culvert inlet and outlet blocked by sediment.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /9-41

Location ID: 432260



Photo #2174 Rill erosion occurring on west end of location



Photo #2177 Cattle guard full of sediment.