

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06641**  
**Date: 11/2/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and crested wheatgrass.



Photo 3. View of cobble run-down in the northern project area. Erosional rilling is occurring around cobbles. Sediment deposition observed at the bottom of the slope (inset). Canada thistles appear to be herbicide treated.



Photo 4. View of reference area comprised of pinyon/juniper woodland with understory of sagebrush, mountain mahogany, squirreltail, and western wheatgrass.



Photos 5/6. View of closed gates after entering (left) and leaving (right) project area.