

Inspection Photos
Operator: BP America
API: 067-06783
Date: 11/2/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and crested wheatgrass.




Photo 3. View of Russian knapweeds, largely appear herbicide-treated, although surviving individuals remain.



Photo 4. View of repaired headcut within the southeastern corner of the project area. Bare soils need additional stabilization.



Photo 5. View of reference area comprised of pinyon/juniper woodland with understory of sagebrush, mountain mahogany, squirreltail, and western wheatgrass.



Photos 6/7. View of closed gates after entering (left) and leaving (right) project area.