

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2020

Submitted Date:

11/05/2020

Document Number:

696103943**FIELD INSPECTION FORM**Loc ID 424859 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424861	WELL	PR	12/01/2018	OW	123-34198	ROBEL 14-28	PA

**General Comment:**This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Abandoned. ALL equipment removed.

Abandoned Battery SE corner GPS coordinates: 40.536876 / -104.559206

Abandoned Battery formerly served 1 Location ID (424859).

(Well(s): 3: Plugged &amp; Abandoned | PA).

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

# 0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: 

Type: Plunger Lift

# 0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: 

Type: Horizontal Heated Separator

# 0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment removed.</a>						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
CRUDE OIL		0						,		
Comment:		Plugged & Abandoned   PA. Equipment removed.								

Corrective Action:				Date:	
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 424861 Type: WELL API Number: 123-34198 Status: PR Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 11/03/2020 at approximately 14:08 hrs. I, Bret Evins, conducted an on-site inspection at:            Operator Name: PDC ENERGY INC            Location Name: Robel 3 Pad /19-28            Location ID: 424859            Well Name: Robel 14-28            API: 05-123-34198            Location County: Weld County, Colorado            Weather: Partly cloudy, dry.</p> <p>While there, I observed:            Well(s): 1: Plugged &amp; Abandoned   PA.            Battery: Abandoned. ALL equipment removed.            Abandoned Battery SE corner GPS coordinates: 40.536876 / -104.559206</p> <p>Abandoned Battery formerly served 1 Location ID (424859).            (Well(s): 3: Plugged &amp; Abandoned   PA).</p> <p>WELL STATUS COMMENT:            Plugged &amp; Abandoned   PA.            Well appears to be cut / capped.            Form 6 doc. #402316886 indicates plugging, cut/cap date: 01/22/2020. Approval Pending.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/04/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103944	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5284870">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5284870</a>