

## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173



Colorado Oil and Gas Conservation Commission  
40.11117, -104.89332, 1508.3m  
Nov 5, 2020 14:30:57



Colorado Oil and Gas Conservation Commission  
40.11091, -104.89363, 1513.4m  
Nov 5, 2020 14:31:30

**Photo 2 Energy Minerals Unit B#1 pumping unit Well is SI**

**Photo 2 Energy Minerals Unit B#1 loc pic**



## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173



**Photo 3 Marvin E. Schutt Unit 1 Treating Facility loc pic**



**Photo 4 production equipment. Pilot does not appear to be lit on ECD and is venting gas.**



## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173




**Photo 5 TNK BTRY**



**Photo 6 HOZ sep Mechanical issue: piping appear to be wet and seeping.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1 Treating facility**  
**Facility ID: 467173**



Colorado Oil and Gas Conservation Commission  
40.11133, -104.89169, 1509.9m  
Nov 5, 2020 14:37:43

**Photo 7 open ended piping and Unmarked not LOTO risers on two unused meter runs.**



Colorado Oil and Gas Conservation Commission  
40.11157, -104.89171, 1511.9m  
Nov 5, 2020 14:40:31

**Photo 8 Mechanical issue: back side load lines leaking south crude oil tank actively leaking . Stained soil under each 2" line on crude oil tanks.**

## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173



**Photo 10 2" line on crude oil tank actively leaking.**



**Photo 11 Stained soil from leaking 2" crude oil line.**



## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173



**Photo 12 unused equipment: piping and guards on location.**



**Photo 13 BMP around material from spill remediation not adequate.**



## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173



**Photo 14 no BMP's around spill remediation in place. No safety fence.**



**Photo 15 Flow lines in excavation not capped or bull plugged and damaged. Stained soil from flow lines leaking.**



## Inspection Photos

Location Name: Marvin E Schutt Unit #1 Treating facility

Facility ID: 467173



**Photo 16 15 Flow lines in excavation not capped or bull plugged and damaged. Stained soil from flow lines leaking.**



**Photo 17 Debris: Dead weeds on location.**