

## Inspection Photos

Location Name: GUNNISON ENERGY LLC HOTCHKISS FEDERAL 1289 #18-22A /18-22A PAD

Location ID: 324483



Photo #2198 from entrance to location.



Photo #2199 from entrance to location.



## Inspection Photos

Location Name: GUNNISON ENERGY LLC HOTCHKISS FEDERAL 1289 #18-22A /18-22A PAD

Location ID: 324483



**Photo #2200 Chemical tank NFPA label weathered and not legible.**



**Photo #2201 Multiple places with debris inside tank containment.**



## Inspection Photos

Location Name: GUNNISON ENERGY LLC HOTCHKISS FEDERAL 1289 #18-22A /18-22A PAD

Location ID: 324483



**Photo #2202 Multiple places with debris inside tank containment.**



**Photo #2203 Debris on East side of tank containment berm.**



## Inspection Photos

Location Name: GUNNISON ENERGY LLC HOTCHKISS FEDERAL 1289 #18-22A /18-22A PAD

Location ID: 324483



**Photo #2207 Rill erosion occurring in ditch at inlet to culvert.**



**Photo #2204 culvert inlet.**



## Inspection Photos

Location Name: GUNNISON ENERGY LLC HOTCHKISS FEDERAL 1289 #18-22A /18-22A PAD

Location ID: 324483



Photo #2205 Culvert outlet.



Photo #2206 Sediment present in cattle guard.