

# Inspection Photos

Operator: Hilcorp Energy  
API: 067-08199  
Date: 11/5/2020



Photo 1. View of the reclaimed access from the beginning, facing along the road alignment. Reference area vegetation is comprised of a mosaic of gambel oak shrubland, with ponderosa pine, pinyon and juniper trees, shrubs such as mountain mahogany, and grasses/forbs such as rocky mountain penstemon, squirreltail, and field sedge.



Photo 2. View of work conducted where erosional head-cut was observed during an earlier reclamation inspection. Bare soils are not protected, and will likely rapidly erode.



Photo 3. View of disturbed soils at the bank of erosional repair. Seeding is not apparent.



Photo 4. View of Canada thistles within the northern project area. Some appear to be herbicide-treated, others are surviving. 1000s of individuals observed.



Photo 5. View of the project area from the southwestern corner facing center.



Photo 6. View of the western project area from the southwestern corner facing northward.