

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2020

Submitted Date:

11/06/2020

Document Number:

700701841

FIELD INSPECTION FORM

Loc ID 335120 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291271	WELL	PR	11/20/2007	GW	045-14322	GEISKE 43C-26-692	PR
291273	WELL	PR	11/21/2007	GW	045-14323	GEISKE 42A-26-692	PR
291308	WELL	PR	05/09/2013	GW	045-14330	GEISKE 32B-26-692	PR
291314	WELL	PR	11/24/2007	GW	045-14325	GEISKE 32D-26-692	PR
297963	WELL	PR	05/21/2009	GW	045-17004	GEISKE 41B-26-692	PR
297964	WELL	PR	05/21/2009	GW	045-17005	GEISKE 41A-26-692	PR
297965	WELL	PR	05/15/2009	GW	045-17006	GEISKE 42C-26-692	PR
297966	WELL	PR	05/15/2009	GW	045-17007	GEISKE 42D-26-692	PR
297967	WELL	PR	05/15/2009	GW	045-17008	GEISKE 43D-26-692	PR
297968	WELL	PR	05/18/2009	GW	045-17009	GEISKE 32C-26-692	PR
297969	WELL	PR	05/18/2009	GW	045-17010	GEISKE 42B-26-692	PR

General Comment:

[COGCC Inspection Report Summary](#)
On Friday 11/6/20 at approximately 1030, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Geiski, at Location # 335120 in Garfield county Colorado. While there, I observed normal production operations. All meters have been calibrated on location within the past year. During this inspection the following possible compliance issues were observed:

- Lack of tracking controls

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:		corrective date
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 14	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 11	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 11	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	chemical tanks at well heads	
Corrective Action:		Date:
Type: Horizontal Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 15	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	HEATED STEEL AST		
Comment:	two (2) tanks are in a separate metal containment				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	291271	Type:	WELL	API Number:	045-14322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291273	Type:	WELL	API Number:	045-14323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291308	Type:	WELL	API Number:	045-14330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291314	Type:	WELL	API Number:	045-14325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297963	Type:	WELL	API Number:	045-17004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297964	Type:	WELL	API Number:	045-17005	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297965	Type:	WELL	API Number:	045-17006	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297966	Type:	WELL	API Number:	045-17007	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 297967 Type: WELL API Number: 045-17008 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 297968 Type: WELL API Number: 045-17009 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 297969 Type: WELL API Number: 045-17010 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Culverts				
Berms		Check Dams				

Comment: [Lack of tracking controls](#)

Corrective Action: [Control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 11/27/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701846	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5286516