

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2020

Submitted Date:

11/05/2020

Document Number:

699501861

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
319692 _____ MEDINA, JUSTIN _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
,		dnr_cogccenforcement@state.co.us	
Espinosa, Bill		billespinosa30@yahoo.com	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200918	WELL	SI	11/01/2019	GW	001-06321	STATE OF COLORADO P 1	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil under ECD see pic 4,5		
Corrective Action:	Comply with 603 F.	Date:	12/05/2020
Type	OTHER		
Comment:	Flaring of natural gas observed on location during inspection. During time of inspection ECD was burning gas. See video/pic 3,4,5,6, COGCC data shows that well is reporing as shut in while flaring gas.		
Corrective Action:	Gas being vented or flared during non-upset condition without prior approval from COGCC.	Date:	11/05/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Prime Mover	# 1	electric motor			
Bird Protectors	# 1				
Ancillary equipment	# 1	electric			
Horizontal Heated Separator	# 1				
Pump Jack	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tank			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 200918 Type: WELL API Number: 001-06321 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 11/5/20 at approximately 1445 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- State of Colorado P1 Company Name- Renegade oil and gas API- 05-001-06321 In Adams County Colorado. While there, I observed producing well During this inspection the following possible compliance issues were observed: Flaring of natural gas observed on location during inspection. During time of inspection ECD was burning gas. See video/pic 3,4,5,6 COGCC data shows that well is reporting as Shut In while flaring gas Gas being vented or flared during non-upset condition without prior approval from COGCC. 11/5/20 Stained soil under ECD see pic 4,5 Comply with 603 F.12/5/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection weather conditions were sunny and calm. This is a summary of inspection report.</p>	medinaj	11/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501862	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5286646
699501863	video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5286647