

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2020

Submitted Date:

11/09/2020

Document Number:

690200798**FIELD INSPECTION FORM**Loc ID 477611 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10720Name of Operator: KODA EXPLORATION LLCAddress: 2443 SOUTH UNIVERSITY BLVD 215City: DENVER State: CO Zip: 80210**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ELGERD ANDERS		elgerd@comcast.net	
SULLIVAN RYAN		rsullivantc@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477612	WELL	XX	08/10/2020		073-06776	WHP Misty 2-7	CI

**General Comment:**

This is a construction inspection of the WHP Misty #2-7 location.  
See attached photos and additional details within this report.

**Location Construction**Location ID: 477612 CDP: \_\_\_\_\_

Comment: The topsoil has been salvaged and stored around the perimeter of the location. The topsoil must be stabilized and protected from degradation and erosion. The topsoil was machine tracked however, tracking is only a short term temporary control. The topsoil is not properly stabilized and is susceptible to erosion.

Corrective Action: Comply with 1002.c

Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

BERMS	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

SLOPE ROUGHENING	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

### **On Site Inspection (305):**

#### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

#### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

#### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

#### Summary of Landowner Issues:

#### Summary of Operator Response to Landowner Issues:

#### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

### **COGCC Comments**

Comment	User	Date
Interim reclamation should be performed soon after drilling completion and before the next growing season to facilitate stabilization and revegetation.	CostaR	11/09/2020
It appeared drilling had commenced at the location and equipment was in process of being moved to the other nearby location.	CostaR	11/09/2020

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690200800	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5286906">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5286906</a>